

AMENDMENTS TO THE SPECIFICATION

Please replace Paragraph [0009] with the following paragraph rewritten in amendment format:

[0009] Further, as the I/O terminals 781 of the circuit board 7 are gold plated on the surface thereof, at the points where they come into contact with the connector electrodes of the rubber connector 60, the contact resistance is small while the rubber connector 60 is compressedly connected therebetween and resistance variation over time hardly occurs; whereas, as the I/O terminals 481 of the liquid crystal panel 400 are formed of ITO film, at the points where the I/O terminals 481 of the liquid crystal panel 400 come into contact with the connector electrodes of a rubber connector [[79]] 60, disadvantages occur such as the contact resistance being large only while being compressedly connected therebetween and the resistance increasing as time passes. Such contact resistance problems, when display is carried out by means of the liquid crystal panel 400, cause problems such as the panel not illuminating or illuminating dimly.